

PALATINE SHELL SERVICE INC.					Sub Estimate For Or
7 E. PALATINE RD. PALATINE, IL. 60067 Phone: 847-358-4299 Fax: 847-358-4332 **OVER 50 YEARS OF SERVICE**					059376
Estimate for Services					Estimate Date : 2/9/2022
Starks, Alex 440 W palatine Rd Palatine, IL 60067 Cellular: 224-578-6827					2011 Dodge - Charger SE - 3.6L,V6 (220CI) VIN(G) Lic #: Z119489 - IL Odom. In: 0
					VIN #: 2B3CL3CG2 BH511434
Part Description	Qty	Sale	Ext	Labor Description	Extended
Control Arm with Ball Joint - Front Lower	1.00	207.71	207.71	CONTROL ARM - Remove & Replace - RWD Upper BOTH SIDES	360.00
Control Arm with Ball Joint - Front Left Lower	1.00	207.71	207.71	CONTROL ARM - Remove & Replace - RWD Lower, Both Sides	360.00
Control Arm with Ball Joint - Front Left Upper	1.00	263.96	263.96	TENSION STRUT - Remove & Replace - Both	240.00
Control Arm with Ball Joint - Front Right Upper	1.00	263.96	263.96	BALL JOINT - Remove & Replace - RWD Lower, Both Sides	840.00
Control Arm - Front Lower	2.00	185.73	371.46	TIE ROD &/OR END - Remove & Replace - Outer, Both Sides	240.00
Ball Joint - Front Lower	2.00	47.66	95.32	STABILIZER BAR CONTROL LINK - Remove & Replace - Both Sides	120.00
Tie Rod End - Outer	2.00	58.66	117.32	SHOCK &/OR STRUT ASSEMBLY - Remove & Install or Remove & Replace - RWD Both Sides - [DOES NOT include disassemble or alignment]	216.00
Strut - Modular Assembly - Quick Strut - Front	2.00	281.16	562.32	ROAD TEST VEHICLE, Check all suspension and steering parts for wear. Check tire pressure and condition. Check riding height, Check alignment of all four wheels. Adjust caster, camber, toe-in, and thrust angle as needed on all four wheels. Center steering wheel	
Sway Bar Link - Front	2.00	70.68	141.36	DRIVESHAFT COUPLER - Removal & Installation - RWD - [Includes: R&I Exhaust System.]	312.00
BOLTS	1.00	40.00	40.00	FOUR WHEEL ALIGNMENT	104.95
Driveshaft Coupler (Flex Disc) Kit	1.00	194.16	194.16		
<i>N/o Rear Brakes</i>					
Parts/Supplies: 2,465.28	Labor: 2,792.95	HazMat/Fees: 0.00	Tax: 246.53	Total: \$ 5,504.76	
THANK YOU - WWW.PALATINESHELLSERVICE.COM					
I hereby authorize you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Any vehicle not picked up three days after repairs are completed are subject to a daily storage fee of twenty five dollars from the day of completion. Unless prior arrangements are made.					
Signature _____ Date _____ Time _____ Kathy, Dina					
Page 1 of 1 Copyright © 2022 Mitchell Repair Information Company, LLC. Author 4.08.2219e					

PALATINE SHELL SERVICE INC. 7 E. PALATINE RD. PALATINE, IL 60067 Phone: 847-358-4299 Fax: 847-358-4332 **OVER 50 YEARS OF SERVICE**					INVOICE 59376												
INVOICE					Printed Date: 02/09/2022 Work Completed: 02/09/2022												
Starks, Alex 440 W palatine Rd Palatine, IL 60067 Cellular 224-578-6827					VIN #: 2B3CL3CG2 BH511434 Lic #: Z119489 Odometer In : 0 Hat #: 18												
Part Description	Qty	Sale	Ext	Labor Description	Ext												
				CHECK GROWLING NOISE WHEN ACCELERATING NEEDS ALL FRONT END STEERING AND SUSPENSION COMPONENTS. FRONT LOWER BALL JOINTS, UPPER CONTROL ARMS, OUTER TIE RODS, LOWER CONTROL ARMS, STRUTS, LINKS, REAR DRIVE AXLE COUPLER COMING APART. NEEDS REAR PADS AND ROTORS. ESTIMATE ATTACHED. CUSTOMER ADVISED MAY NOT BE WORTH FIXING AND CAR IS UNSAFE TO DRIVE AS IS.	n/c												
[Payments -] THANK YOU - WWW.PALATINESHELLSERVICE.COM I hereby authorize you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Any vehicle not picked up three days after repairs are completed are subject to a daily storage fee of twenty five dollars from the day of completion. Unless prior arrangements are made.					<table border="1"><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Sub:</td><td>0.00</td></tr><tr><td>Tax:</td><td>0.00</td></tr><tr><td>Total:</td><td>\$0.00</td></tr><tr><td>Bal Due:</td><td>\$0.00</td></tr></table> <p>Customer Number : 7915</p>	Labor:	0.00	Parts:	0.00	Sub:	0.00	Tax:	0.00	Total:	\$0.00	Bal Due:	\$0.00
Labor:	0.00																
Parts:	0.00																
Sub:	0.00																
Tax:	0.00																
Total:	\$0.00																
Bal Due:	\$0.00																
Vehicle Received: 2/9/2022 Signature _____ Date, _____																	
Visit us on the web: www.palatineshellservice.com Service Advisor: Karlos, Sinc. Tech: Benavides, Juan					Email Address: paltineshellservice@gmail.com Page 1 of 1 Copyright © 2022 Mitchell Repair Information Company, LLC (mvr) 5.12.29n												